

FACILITIES REQUEST 2017:

Program or Service Unit:

Submitter:

Submitter Telephone:

Submitter e-mail:

Funding Source:

Needs Funding	<input checked="" type="checkbox"/>
Grant	<input type="checkbox"/>
Department	<input type="checkbox"/>

If you have multiple requests, please submit multiple forms.

Please share as many details as possible such as room location(s), type of facilities request, remodel or construction request, safety concern, or furniture request. If you have a cost estimate, that would be helpful, we will contact you for more details.

I am requesting the following facilities need:

FA20

1. There are five sinks in the ceramics studio. All of them should have a clay trap on them to prevent clay from being washed down the drain and clogging the pipes. Currently there are no traps on the sink. The floor drains have over flown several times this semester because of this problem. These run around \$150. - \$200. Each so would cost \$750. - \$1000. To set this up for the studio.
2. We need to have the walls repaired and painted in the glazing area FA 21 and the chemical lab FA21a. The walls are now a dingy blue colors with many holes in the wall.
3. We need the lights behind the kilns in FA21c repaired. Currently there is just exposed wire sticking out from the wall. We need these lights to see what we are doing when we are firing the kilns. It is also a safety hazard to have exposed wires sticking out from the wall.
4. We need to have all the Ballasts and lights checked and replaced as needed as many currently don't work or flicker. This is a distraction to the learning environment and should be addressed.
5. The faucets in the ceramics area should be checked and replaced as needed. Currently most of the sinks drip when turned off. At the very least all the seals should be checked and replaced if not the whole faucet.
6. Replace all water damaged ceiling tiles. There are several tiles that have water stains in them that need to be replaced. There are also some that were removed when there was a recent water leak. They were never replaced so we